

Release Note for Vigor2700 Series

Firmware Version: 2.8.4

Release Date: May 2, 2014

Applied Models:

**Vigor2700, Vigor2700G, Vigor2700V(2S/2S1L), Vigor2700VG(2S/2S1L),
Vigor2700Gi (Annex B), Vigor2700VGi (Annex B)**

- File and Modem Code

(1)For Annex A Model,

- "v2k7v_a_284" is used for modem code 121201. (Standard)
- "v2k7v_a1_284" is used for modem code 113111.
- "v2k7v_a2_284" is used for modem code 131701. (Recommended for UK-SEG)
- "v2k7v_a3_284" is used for modem code 1401201. (Recommended for USA or for G.lite environment)
- "v2k7v_a4_284" is used for modem code 1411301.
- "v2k7v_a5_284" is used for modem code 142201.

(2)For Annex B Model,

- "v2k7v_b_284" is used for modem code 131812. (Standard)
- "v2k7v_b1_284" is used for modem code 113112.
- "v2k7v_b2_284" is used for modem code 1211202.
- "v2k7v_b3_284" is used for modem code 1311302. (Recommended for Germany)
- "v2k7v_b4_284" is used for modem code 1401302.
- "v2k7v_b5_284" is used for modem code 1411402.
- "v2k7v_b6_284" is used for modem code 142112. (Support T1.413 Annex B, recommended for Spain)
- "v2k7v_b7_284" is used for modem code 142402.

New Features

- None

Improvement

- Corrected: Security vulnerability for WLAN reported by CERT.
- Corrected: Solve the buffer leakage problem when handling SNMPv2c "getbulk" request.
- Corrected: Solve the memory leakage problem for SIP ACK message.

- Corrected: A local buffer overwrite problem occurs when "*ip igmp_proxy status*" and "*ip igmp_snoop status*" telnet commands are used.
- Corrected: Can not remove old password after setting new password.
- Corrected: "*ip route add*" telnet command can not work.
- Improved: Change PPP CHAP timeout to 60 seconds.
- Improved: Remove PPPoE MTU size limitation for Vietnam.
- Improved: Change "Session Version" in SIP re-invite packet of FAX.
- Improved: Add contact header for SIP SUBSCRIBE message.
- Improved: Add two telnet commands, "*voip dsp jitterBuffer*" & "*voip dsp flash*".

Known Issue

- None

Notes

Modifications

- None