

## Release Note for Vigor2762 Series

Firmware Version:	3.9.1
Release Type:	Normal
Applied Models:	Vigor2762, Vigor2762n, Vigor2762ac, Vigor2762Vac

Vigor2762 series, the high speed router, are perfectly complied with VDSL2 environment including Vigor2762n and Vigor2762ac for speed-wanted customers. With high throughput performance and secured broadband connectivity provided by Vigor2762 series, you can simultaneously engage these bandwidth-intensive applications, such as high-definition video streaming, online gaming, and Internet telephony / access.

### File and Modem Code

**Note:** For DSL models, there will be two folders: STD and MDM. The files in MDM folder named folder include different modem codes. If you're using a VDSL line, MDM firmware may brings out better performance.

Available modem codes for Annex A/Annex B are displayed as follows:

#### For Annex A Model,

- "Vigor2762\_v3.9.1\_STD.zip" is used for modem code 776d07\_772801 & 774307\_771801
- "Vigor2762\_v3.9.1\_MDM1.zip" is used for modem code 779517\_773F01 & 77B507\_775401.
- "Vigor2762\_v3.9.1\_MDM2.zip" is used for modem code 77B506\_775401 & 778C06\_773F01.

#### For Annex B Model,

- "Vigor2762\_v3.9.1\_STD.zip" is used for modem code 773306\_771502 & 773307\_771C02.
- "Vigor2762\_v3.9.1\_MDM1.zip" is used for modem code 779B06\_774F02 & 779B07\_774C12.
- "Vigor2762\_v3.9.1\_MDM2.zip" is used for modem code 779906\_774402 & 779B06\_774C02.

### New Features

- None.

## Improvement

- Improved: The IP group can be used as source IP on NAT >> Open Ports.
- Improved: The IP address can be selected as a provider host in customized DDNS profile.
- Improved: Support SIP alias number.
- Improved: Add the TR-069 parameter of WAN1 >> PPPoE >> Fallback account.
- Improved: Add the TR-069 parameter to execute the telnet command.
- Corrected: Unable to accept VPN remote dial-in users when "change default route to this VPN tunnel" was enabled for the LAN to LAN.
- Corrected: Issues related to IGMP.
- Corrected: Unable to upgrade APPE signature.
- Corrected: NAT performance was low when the data filter was disabled in the firewall.
- Corrected: Router crashed on EAP\_PEAP/MSCHAPv2 authentication request.
- Corrected: Unable to use port 1194 even OpenVPN service was disabled.
- Corrected: After 21 VPNs are up, the router starts to reboot every 2 mins
- Corrected: Failed to create IKEv2 EAP connection from Windows 10 when using self-signed CA.
- Corrected: WLAN schedule could not be set to disable WiFi Signal.
- Corrected: The router would reboot when OpenVPN client was connecting.
- Corrected: Unable to display specific configuration file for menu options.
- Corrected: When there was more than one NATed VPN tunnel established, policy routes set with different NATed VPN interface did not work.
- Corrected: Vigor router would reboot after disconnecting SSH session abnormally.
- Corrected: Vigor router would constantly reboot after restoring with the specific configuration.

## Known Issue

- None.