Release Note for Vigor2763 Series

Firmware Version:	4.4.5.1
Release Type:	Normal - Upgrade recommended when convenient
Applied Models:	Vigor2763, Vigor2763ac, Vigor2763Vac

New Features

- None.

Improvement

- Improved: Password mechanism changed to force admin to change the password from the default password.
- Improved: Follows RFC4028 standards to prevent SIP registration errors from repeated attempts.
- Improved: Support an option of excluding the DFS channels for the Wireless LAN Auto Channel Select function.
- Improved: Add the minimum RSSI for Band Steering.
- Improved: Support customize http port for user-defined DDNS.
- Improved: Add a new option (Discord) on CSM>>APP Enforcement Profile.
- Improved: Improve the TR-069 file transfer process (do not send FIN/ ACK directly when receiving the TransferCompleteResponse from the ACS).
- Corrected: An issue with failure to work for WAN Failover.
- Corrected: An issue with the reboot loop caused by enabling QoS.
- Corrected: An issue with the display error for the time zone for Athens.
- Corrected: An issue with no HTTPS access via LAN to LAN VPN NAT IP.
- Corrected: An issue that the Hotspot Web Portal stopped working after some time.
- Corrected: An issue with failure to apply the SIP account when set by provisioning.
- Corrected: An issue with failure to add more remote subnet in LAN to LAN profiles.
- Corrected: An issue that WireGuard Dial-in Profile could not save due to a username error.
- Corrected: An issue that the vigor router rebooted when airplay was used by Wi-Fi connected device.
- Corrected: An issue with failure to correctly display the Firewall>>Defense Setup>> IP White/Black List page.
- Corrected: An issue that CPE stayed in boot loop after firmware upgrade if the system parameter 15 was enabled.

- Corrected: An issue of replying the ICMP fragment needed packet with the wrong source port when receiving an SIP INVITE packet size greater than 1492 bytes with DF flag.

Known Issue

- None.

File and Modem Code

- "Vigor2763_v4.4.5.1_STD.zip" provides Annex A modem code 77B507_775401, 77B506_775401 and Annex B 779B07_774C12, 779906_774402
- " Vigor2763_v4.4.5.1_MDM1.zip " is used for modem code77C817_775A11 77C717_775A11 and Annex B 77C717_775A12, 779B07_774C12