

Release Note for Vigor120 Series

Firmware Version: 3.2.6

Built Date: May 24, 2011

Applied Models:

Vigor120

- File and Modem Code

(1)For Annex A Model,

- "v12x_a_v326" is used for modem code 321311. (Standard)
- "v12x_a1_v326" is used for modem code 310801.
- "v12x_a2_v326" is used for modem code 310811.
- "v12x_a3_v326" is used for modem code 3211201
- "v12x_a4_v326" is used for modem code 332201.
- "v12x_a5_v326" is used for modem code 343601.
- "v12x_a6_v326" is used for modem code 343701 (recommended for Italy).
- "v12x_a7_v326" is used for modem code 3431301.
- "v12x_a8_v326" is used for modem code 344001.
- "v12x_a9_v326" is used for modem code 344101.
- "v12x_a10_v326" is used for modem code 3471101.

(2)For Annex B Model,

- "v12x_b_v326" is used for modem code 311112. (Standard)
- "v12x_b1_v326" is used for modem code 3101212.
- "v12x_b2_v326" is used for modem code 3101332.
- "v12x_b3_v326" is used for modem code 311102.
- "v12x_b4_v326" is used for modem code 346302.

New Features

- Support DSL VPI/VCI auto-detection for Mexico.

Improvement

- Corrected: Meet crash problem while clicking **Firewall>>General Setup** page or view **Filter Rule**.

- Corrected: Error occurs for the parameter of Open Port in TR-069.
- Corrected: LAN TX/RX (transmission/receiving) statistics are “0” for TR-069.
- Improved: Allow to modify SMTP port number.
- Improved: Add a **Delete** button for removing the static route.

Known Issue

- None

Notes

Modifications

- None