Release Note for Vigor120 Series

Firmware Version: 3.2.7 Release Date: February 25, 2015 Applied Models: Vigor120

- File and Modem Code
 - (1)For Annex A Model,
 - ➤ "v12x_a_v327" is used for modem code 321311. (Standard)
 - \triangleright "v12x_a1_v327" is used for modem code 310801.
 - \rightarrow "v12x_a2_v327" is used for modem code 310811.
 - ➤ "v12x_a3_v327" is used for modem code 3211201
 - \rightarrow "v12x_a4_v327" is used for modem code 332201.
 - \triangleright "v12x_a5_v327" is used for modem code 343601.
 - ➤ "v12x_a6_v327" is used for modem code 343701 (recommended for Italy).
 - \rightarrow "v12x_a7_v327" is used for modem code 3431301.
 - ➤ "v12x_a8_v327" is used for modem code 344001.
 - \rightarrow "v12x_a9_v327" is used for modem code 344101.
 - ➤ "v12x_a10_v327" is used for modem code 3471101.

(2) For Annex B Model,

- ➤ "v12x_b_v327" is used for modem code 311112. (Standard)
- ➤ "v12x_b1_v327" is used for modem code 3101212.
- ➤ "v12x_b2_v327" is used for modem code 3101332.
- \triangleright "v12x_b3_v327" is used for modem code 311102.
- \triangleright "v12x_b4_v327" is used for modem code 346302.

New Features

 Support to display DSL status of Vigor120 on System Status page of Vigor router behind Vigor120.

Improvement

• Improved: Some routers may fail to create PPPoE connection behind Vigor120.

• Corrected: After registered to SIP server via Vigor 120, SIP phone might not work normally after a period of using.

Known Issue

None

Notes

Modifications

None