

## Release Note for Vigor120 Series

**Firmware Version: 3.2.4.3**

**Built Date: April 1, 2010**

**Applied Models:  
Vigor120**

---

- File and Modem Code
  - (1)For Annex A Model,
    - "v120\_a\_v3243" is used for modem code 321311. (Standard)
    - "v120\_a1\_v3243" is used for modem code 310801.
    - "v120\_a2\_v3243" is used for modem code 310811.
    - "v120\_a3\_v3243" is used for modem code 3211201
    - "v120\_a4\_v3243" is used for modem code 332201.
    - "v120\_a5\_v3243" is used for modem code 343601.
    - "v120\_a6\_v3243" is used for modem code 343701 (recommended for Italy).
    - "v120\_a7\_v3243" is used for modem code 3431301.
    - "v120\_a8\_v3243" is used for modem code 344001.
    - "v120\_a9\_v3243" is used for modem code 344101.

## New Features

- None.

## Improvement

- Corrected: disconnection problem occurred for *2ndlife* and *ichat* while WAN interface is PPPoA mode.
- Corrected: can not work with IPv6 when the router is running with PPPoA pass-through mode.
- Improved: modify the page error in certain popped up window.
- Improved: an error occurred while the user uses '\' as Pre-Shared Key.

## **Known Issue**

- None

## **Notes**

### ***Modifications***

- None