

Release Note for Vigor130 Series

Firmware Version: 3.7.5.1
Release Date: June 16, 2014
Applied Models:
Vigor130

- File and Modem Code
 - (1)For Annex A Model,
 - VDSL 548006 & ADSL 544401 (Standard)
 - VDSL 547916 & ADSL 544411 will be used for Modem 1.
 - VDSL 550e06 & ADSL 551001 will be used for Modem 2.
 - VDSL 551506 & ADSL 551501 will be used for Modem 3.
 - VDSL 567517 & ADSL 562301 will be used for Modem 4 (G.Vector).
 - VDSL 571a17 & ADSL 570111 will be used for Modem 5 (G.Vector) recommended for Netherland ISP - KPN.
 - VDSL 572d07 & ADSL 570e01 will be used for Modem 6 (G.Vector) recommended for Netherland ISP - KPN.
 - (2)For Annex B Model,
 - VDSL 548006 & ADSL 544512 (Standard)
 - VDSL 542016 & ADSL 535112 will be used for Modem 1.
 - VDSL 533d06 & ADSL 535902 will be used for Modem 2.
 - VDSL 548006 & ADSL 544512 will be used for Modem 3.
 - VDSL 565606 & ADSL 567002 will be used for Modem 4, 5, 6 (G.Vector) recommended for Netherland ISP - KPN.

New Features

- Add new feature, Management>>Device Management.
- Supported TR069 over SSL.
- Supported various ADSL/VDSL parameter display using telnet command (>VDSL status or >ADSL status).

Improvement

- Corrected: Correct some issues for VDSL2 G.Vector.
- Corrected a router SSH server stability issue.
- Corrected router stability issues with NMAP scan.
- Corrected: PPPoE passthrough didn't work after loading *.rst to Vigor130.
- Corrected: VPN passthrough didn't work when VPN server is on the LAN-side.
- Corrected: UPnP application might cause router to reboot.
- Improved: DHCP Relay feature.
- Improved: Allow VLAN tagged traffic to pass through the router configured as bridge.
- Improved: DSL last showtime mechanism.

Known Issue

- None

Notes

Modifications

- None