

## Release Note for Vigor167

Firmware Version:	5.2.5
Release Type:	Normal - Upgrade recommended when convenient
Applied Models:	Vigor167

### New Features

- None.

### Improvement

- Improved: Password mechanism changed to force admin to change the password from the default password.
- Improved: Add a note to notify users that the Tone Information for the VDSL35b line type cannot be entirely displayed on the Monitoring>>DSL Status page.
- Corrected: An issue with failure to show (ADSL/VDSL) SNMP information.
- Corrected: An issue with VDSL35b speed dropped to 17a after a few minutes.
- Corrected: An issue with failure to login from LAN via the hostname when WAN login was disabled for admin account.
- Corrected: An issue with failure to set Username and Password with special characters for TR-069 (System Management>>Management).

### Known Issue

- To enhance security, firmware version 5.2.3 and the later version modified some system default values and implemented RE pattern checks and command injection checks on system parameters, fields, and values. These changes may cause configuration incompatibilities. Customers attempting to upgrade to the new firmware version may encounter issues such as the firmware version not changing after the upgrade or being unable to import previously backed-up configuration files. In such cases, we recommend that customers reset to factory default settings and reconfigure to resolve the issue.

### File and Modem Code

- "Vigor167\_v5.2.5.zip" provides modem code 5.12.31.0, and 5.12.18.17.