

## Release Note for Vigor2110 Series

**Firmware Version: 3.3.1.2**  
**Built Date: October, 29, 2009**  
**Applied Models:**  
**Vigor2110, Vigor2110n, Vigor2110Vn**

---

Please ensure you download and use the latest router tools when upgrading the firmware.

### New Features

- Add new physical type for "Copper" or "Fiber" for Internet Access on WUI.

### Improvement

- Improved: 3G upload performance for some special cases.
- Corrected: When a user makes a call transfer to local phone, the router will reboot automatically. It is abnormal. Now a busy tone will be returned while making a call transfer to local phone.
- Corrected: Open WAN IP Alias in DHCP page.
- Corrected: Redialing a phone to PSTN via "digit map" and "phone book" will cause loop tone and can't be stopped when PSTN is in use.
- Corrected: Flashing LED if SIP phones are in use and PSTN is incoming.
- Corrected: Problem of Model Name shown in WUI and TR069.
- Corrected: Close TR069 port if the router is disabled.
- Corrected: Inform with default WAN connection *ExternalIPAddress* for Tr069.
- Corrected: Can't hear anything when a phone is dialed to an *iptel* account with SIP number.
- Corrected: VPN pass through is not available for users in England (SEG.) at present.
- Corrected: Got undefined error when set PPTP configuration on Quick Start Wizard.
- Corrected: Got undefined error in Ping Diagnosis WUI.
- Corrected: Got a warning message in Diagnostics >> Traffic Graph WUI
- Corrected: Cannot reset session of date flow monitor while using "portmuptime -f" command.

## Known Issue

- None

## Notes

### *Modifications*

- None