

Release Note for Vigor2133 Series

Firmware Version:	3.8.9.1
Release Type:	Normal
Applied Models:	Vigor2133/Vigor2133n/Vigor2133ac/Vigor2133Vac/Vigor2133FVac

Vigor2133 features advanced bandwidth control mechanism such as IP-layer, QoS, NAT Session Limitation, Bandwidth Borrowed, etc., to allow easy, flexible, reliable access control and bandwidth management.

New Features

- None.

Improvement

- Corrected: The settings in APP Enforcement Profiles were messed up, after upgrading the firmware to Version 3.8.9.
Suggestion: Choose one of the following methods to upgrade the router firmware.
 - Upgrade the firmware from the old version to new version (V3.8.9.1) directly.
 - Upgrade the firmware to V3.8.9 by using “x.all”. Do not modify the APP profile configuration and then upgrade the firmware to 3.8.9.1.
- Corrected: Vigor router reboot randomly due to incompliant with TR-069 server.
- Corrected: Interface for static routes reported on web user interface (GUI) and telnet (CLI) were inconsistent.

Known Issue

- None.