

Release Note for Vigor2710 Series

Firmware Version: 3.3.6

Built Date: November 12, 2010

Applied Models:

Vigor2710, Vigor2710n, Vigor2710Vn, Vigor2710VDn

- File and Modem Code

(1)For Annex A Model,

- " v2710_a_336" is used for modem code 211011. (Standard)
- " v2710_a1_336" is used for modem code 211801.
- " v2710_a2_336" is used for modem code 2121501.
- " v2710_a3_336" is used for modem code 2211201.
- " v2710_a4_336" is used for modem code 232201. (Recommended for UK – SEG)
- " v2710_a5_336" is used for modem code 243601.
- " v2710_a6_336" is used for modem code 243701.
- " v2710_a8_336" is used for modem code 244001.
- " v2710_a7_336" is used for modem code 2431301.
- " v2710_a9_336" is used for modem code 2471201.

(2)For Annex B Model,

- " v2710_b_336" is used for modem code 2111112. (Standard)
- " v2710_b1_336" is used for modem code 2111302. (Recommended for Attel Czech only)
- " v2710_b2_336" is used for modem code 2121302 (recommended for Slovskia only).
- " v2710_b4_336" is used for modem code 214702.
- " v2710_b5_336" is used for modem code 2111312.
- " v2710_b6_336" is used for modem code 215202.
- " v2710_b7_336" is used for modem code 246302.

New Features

- Add WCF Service Activation Wizard on WUI.
- Support APPQoS.

Improvement

- Improved: Modify user password for admin operation mode and user operation mode.
- Improved: Samba server cannot display correct German information.
- Improved: WAN detection function for PVC WAN must be added.
- Improved: Shared item added to Bandwidth Limit web page.
- Improved: WAN Inbound Bandwidth and WAN Outbound Bandwidth added for QoS web page.
- Improved: The system must wait for 60 seconds for triggering 3G connection while PPPoE/MPoA mode is disabled and 3G backup mode is enabled.
- Improved: Anonymous calls cannot be blocked.
- Improved: VoIP debug show message cannot be duplicated to SysLog tool.
- Improved: The caller ID of PSTN call cannot be displayed.
- Improved: P2P session control / limit function is not supported.
- Improved: Domain name cannot be used in STUN server IP field in TR-069 web page.
- Improved: SMTP server port number cannot be defined in **System Maintenance>>Syslog / Mail Alert Setup**.
- Improved: **IPSec AES in Phase I** cannot be supported for **Aggressive Mode**.
- Improved: There is no “Browse” button on the Home Folder field on **USB Application >>USB User Management**.

Related Information

- Get the document, please visit <http://www.draytek.com.tw/user/PdInfoDetail.php?Id=84#PdInfo>
- Get the new firmware, please visit not ready
- Get the customer service support, please visit <http://www.draytek.com.tw/user/ContactHeadquarters.php>
- Get the regulatory compliance information <http://www.draytek.com.tw/user/AboutRegulatory.php>
- Get information for global partners <http://www.draytek.com.tw/user/Globalpartners.php>

Known Issue

- None

Notes

Modifications

- None