# **Release Note for Vigor2710 Series**

# Firmware Version: 3.6.5 Release Date: April 26, 2013 Applied Models:

Vigor2710, Vigor2710n, Vigor2710Vn, Vigor2710VDn

- File and Modem Code
  - (1)For Annex A Model,
    - > " v2710\_a\_365" is used for modem code 211011. (Standard)
    - > " v2710 a1 365" is used for modem code 211801.
    - > " v2710\_a2\_365" is used for modem code 2121501.
    - > " v2710\_a3\_365" is used for modem code 2211201.
    - ➤ "v2710\_a4\_365" is used for modem code 232201. (Recommended for UK SEG)
    - > " v2710 a5 365" is used for modem code 243601.
    - > " v2710\_a6\_365" is used for modem code 243701.
    - > " v2710\_a8\_365" is used for modem code 244001.
    - > " v2710\_a7\_365" is used for modem code 2431301.
    - > "v2710\_a9\_365" is used for modem code 2471201.

#### (2) For Annex B Model,

- > " v2710\_b\_365" is used for modem code 2111112. (Standard)
- ➤ "v2710\_b1\_365" is used for modem code 2111302. (Recommended for Attel Czech only)
- ➤ "v2710\_b2\_365" is used for modem code 2121302 (recommended for Slovskia only).
- > " v2710 b4 365" is used for modem code 214702.
- > " v2710 b5 365" is used for modem code 2111312.
- > " v2710 b6 365" is used for modem code 215202.
- > " v2710 b7 365" is used for modem code 246302.

## **New Features**

- Support wireless wizard.
- Support "USB Device Status" for modem, disk, and printer.
- Support "APPE Support List".

# **Improvement**

- Improved: Support Editing DHCP server options (ASCII/Hex) on web user interface.
- Improved: Support DHCP client identifier for some ISP. (DHCP Option 61 with PPP, username/password)
- Improved: Support the DNS 8.8.8.8 for web content feature (WCF) function for authentication
- Improved: Add checkboxes of "Always On" and "Dial On" for IPv6 AICCU.
- Improved: Add VoIP Inter-digit timeout for TR-104.
- Corrected: System crash problem occurs while a user performs Port Scan with AICCU IPv6 LAN IP.
- Corrected: Can not create a second profile in Remote Dial-in User page.
- Corrected: Security risk occurred if unconfigured LAN to LAN or Dial-In user profile is activated.
- Improved: Support special character "-" in SMS/Recipient and WAN/Display Name.

# **Known Issue**

None

## **Notes**

### **Modifications**

None