

## Release Note for Vigor2710 Series

**Firmware Version: 3.6.8**

**Release Date: January 30, 2014**

**Applied Models:**

**Vigor2710, Vigor2710n, Vigor2710Vn, Vigor2710VDn**

---

- File and Modem Code

(1)For Annex A Model,

- " v2710\_a\_368" is used for modem code 211011. (Standard)
- " v2710\_a1\_368" is used for modem code 211801.
- " v2710\_a2\_368" is used for modem code 2121501.
- " v2710\_a3\_368" is used for modem code 2211201.
- " v2710\_a4\_368" is used for modem code 232201. (Recommended for UK – SEG)
- " v2710\_a5\_368" is used for modem code 243601.
- " v2710\_a6\_368" is used for modem code 243701.
- " v2710\_a8\_368" is used for modem code 244001.
- " v2710\_a7\_368" is used for modem code 2431301.
- " v2710\_a9\_368" is used for modem code 2471201.

(2)For Annex B Model,

- " v2710\_b\_368" is used for modem code 2111112. (Standard)
- " v2710\_b1\_368" is used for modem code 2111302. (Recommended for Attel Czech only)
- " v2710\_b2\_368" is used for modem code 2121302 (recommended for Slovskia only).
- " v2710\_b4\_368" is used for modem code 214702.
- " v2710\_b5\_368" is used for modem code 2111312.
- " v2710\_b6\_368" is used for modem code 215202.
- " v2710\_b7\_368" is used for modem code 246302.

## New Features

- None

## Improvement

- Improved: SSL3 now disabled in favour of TLS by default for SSL tunnels and web management.
- Improved: Improve the mechanism of TCP SYN to prevent from being unable to access into web user interface due to abnormal TCP connection in Portugal area.
- Corrected: 3G backup mode can't work after 36 days.
- Corrected: Firewall blocks IPv6 incoming routing traffic.
- Corrected: Wrong SNMP information for OID: 1.3.6.1.2.1.1.1.

## Known Issue

- None

## Notes

### *Modifications*

- None