

## Release Note for Vigor2763 Series

Firmware Version:	4.4.5.6
Release Type:	Normal - Upgrade recommended when convenient
Applied Models:	Vigor2763, Vigor2763ac, Vigor2763Vac

### New Features

- None.

### Improvement

- Improved: Add the memory leak protection.
- Improved: Support displaying RSSI for WiFi clients in the SysLog.
- Improved: Improve a probable memory insufficiency problem by reverting the Country object database to a previous version.
- Corrected: An issue with random wireless disconnection problem.
- Corrected: An issue where traffic could not pass through Multiple SA VPN to Cisco.
- Corrected: An issue where TR-069 settings would not be saved if the router was rebooted.
- Corrected: An issue with failure to create Lets Encrypt certificate with No-IP domain name.
- Corrected: An issue with reboot problem when TR069 parameter tree being read by ACS server.
- Corrected: An issue that changing the 2.4GHz channel from 11 to Auto caused the router to reboot.
- Corrected: An issue that both 2.4G and 5G Wifi stopped functioning when a specific wireless client (ax) connected.
- Corrected: An issue with failure to access the router's Web Interface after some days from the Internet via HTTP or HTTPS.
- Corrected: An issue with the router reboot concerning the USB disk (the Hotspot Web Portal User Database remained functional when the portal feature was disabled).

### Known Issue

- None.

### File and Modem Code

- "Vigor2763\_v4.4.5.6\_STD.zip" provides Annex A modem code 77B507\_775401, 77B506\_775401 and Annex B 779B07\_774C12, 779906\_774402
- "Vigor2763\_v4.4.5.6\_MDM1.zip" is used for modem code 77C817\_775A11 77C717\_775A11 and Annex B 77C717\_775A12, 779B07\_774C12