

Release Note for Vigor2763 Series

Firmware Version:	4.5.3.2
Release Type:	Critical – Upgrade immediately to address urgent security issues or major system risks
Applied Models:	Vigor2763, Vigor2763ac, Vigor2763Vac

New Features

- None.

Improvement

- Improved: Adjust the URL for connecting to MyVigor from auth.draytek.com to auth2.draytek.com.
- Improved: Enhance the Web CGI security.
- Improved: Improve the WiFi Driver Security (CVE-2025-20674).
- Improved: Enhance Content Security Policy (CSP) security by using a randomly generated nonce.
- Corrected: An issue that could cause the router to reboot unexpectedly due to a VoIP attack.
- Corrected: An issue which the router rebooted when importing config exp file.
- Corrected: An issue where changes to the admin username made via TR-069 took effect initially but were not retained after the router was rebooted.
- Corrected: An issue that caused Vigor2765 to be incorrectly identified as the LTE variant after a firmware upgrade and potentially enter a boot loop when a specific USB dongle was connected to USB1.
- Corrected: Issues that may cause unexpected router reboots related to the IKE buffer, TR-069 DNS, IGMP Syslog, OpenSSL, customized DDNS, and wireless mesh nodes.

Known Issue

- None.

File and Modem Code

- "Vigor2763_v4.5.3.2_STD.zip" provides Annex A modem code 77B507_775401, 77B506_775401 and Annex B 779B07_774C12, 779906_774402
- "Vigor2763_v4.5.3.2_MDM1.zip" is used for modem code 77C817_775A11 77C717_775A11 and Annex B 77C717_775A12, 779B07_774C12