Release Note for Vigor2820 Series

Firmware Version: 3.3.7.6
Release Date: January 23, 2015
Applied Models:
Vigor2820/2820V/Vigor2820n/Vigor2820Vn/Vigor2820VS/
Vigor2820VSn

For the users who still use Firmware Version 3.3.5 (and before):

Because the functions and WUI on Firmware Version 3.3.5 (and before) are different with Firmware Version 3.3.7.2 and later, we strongly suggest you to download the file (V3.3.5.2) from the following FTP first.

ftp://ftp.draytek.com/Vigor2820/Firmware/

Upgrade your router with Version 3.3.5.2 first, and last, upgrade the router with Version 3.3.7.2 (or later).

File and Modem Code

(1)For Annex A Model,

- ➤ "v2820_v3376_211011_A" is used for modem code 211011(Standard).
- > "v2820_v3376_232201_A." is used for modem code 232201 (recommended for UK-SEG only).
- > "v2820_v3376_211801_A" is used for modem code 211801.
- > "v2820 v3376 2121501 A" is used for modem code 2121501.
- > "v2820 v3376 2211201 A" is used for modem code 2211201.
- > "v2830 v3376 243601 A" is used for modem code 243601.
- ➤ "v2830_v3376_243701_A" is used for modem code 243701.
- > "v2830 v3376 2431301 A" is used for modem code 2431301.
- > "v2830 v3376 244001 A" is used for modem code 244001.
- ➤ "v2830_v3376_ 2471201_A" is used for modem code 2471201.

(2)For Annex B Model,

- > "v2820_v3376_2111112_B" is used for modem code 2111112. (Standard)
- ➤ "v2830_v3376_ 2121302_B" is used for modem code 2121302.(recommended for Slovakia only)
- ➤ "v2820_v3376_2111302_B" is used for modem code 2111302 (recommended for Czech only).

- ➤ "v2820_v3376_214702_B" is used for modem code 214702.
- > "v2820_v3376_215202_B" is used for modem code 215202.
- ➤ "v2820_v3376_246302_B" is used for modem code 246302.
- > "v2820_v3376_2111312_B" is used for modem code 2111312.

New Features

None.

Improvement

- Corrected: TCP SYN cookie bugs
- Corrected: A VoIP issue, "cannot block anonymous calls with sipgate".

Known Issue

None

Notes

Modifications

None