

Release Note for Vigor2830n V2

Firmware Version: 3.7.4.1
Release Date: September 24, 2014
Applied Models:
Vigor2830n V2

Vigor2830n V2 is an ADSL2+ router. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The gigabit WAN2 and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe.

New Features

- This firmware is dedicated for Vigor2830n V2 only.

Improvement

- Corrected: Vigor router would reboot when accessing Web UI via HTTPS with WAN IP from LAN.
- Corrected: Connection mode for WAN2 cannot be shown correctly in VigorACS SI.
- Corrected: LAN2 Routing Mode didn't reply WAN ARP for LAN Clients like IP Routed Subnet did.
- Corrected: Router randomly reboot when WCF was applied.
- Corrected: Fixed the problem of memory usage after PPPoE disconnection.
- Corrected: Mail Alert did not work with 1und1 SMTP server.
- Corrected: CPE did not add new parameter(s) for working with VigorACS SI version (1.1.5).
- Corrected: Could not show "_" at comment of Bind IP to MAC.
- Improved: Generate a more secure key of AES for APM.

Known Issue

- None

Notes

Modifications

- None