

Release Note for Vigor2850 Series

Firmware Version: 3.6.6.1

Release Date: June 24, 2014

Applied Models:

Vigor2850/Vigor2850n/Vigor2850Vn/ Vigor2850i

Vigor2850 series is a **VDSL2** router with **multi-subnet** for secure and efficient workgroup management. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

- File and Modem Code

(1) VDSL Firmware Version: 1414c3

(2) ADSL for Annex A Model,

- "v2850_a_3661" is used for modem code 211801(Standard).
- "v2850_a2_3661" is used for modem code 2121501.
- "v2850_a3_3661" is used for modem code 2211201.
- "v2850_a4_3661" is used for modem code 232201 (recommended for UK-SEG only)
- "v2850_a5_3661" is used for modem code 243601.
- "v2850_a6_3661" is used for modem code 243701.
- "v2850_a7_3661" is used for modem code 2431301.
- "v2850_a8_3661" is used for modem code 244001.
- "v2850_a9_3661" is used for modem code 2471201.

(3) ADSL for Annex B Model,

- "v2850_b_3661" is used for modem code 2111112. (Standard)
- "v2850_b1_3661" is used for modem code 2111302 (recommended for Czech only)
- "v2850_b2_3661" is used for modem code 2121302.(recommended for Slovakia only)
- "v2850_b4_3661" is used for modem code 214702.
- "v2850_b5_3661" is used for modem code 2111312.
- "v2850_b6_3661" is used for modem code 215202.
- "v2850_b7_3661" is used for modem code 246302.

New Features

- None.

Improvement

- Corrected: CVE-2014-0224 CCS injection vulnerability.

Known Issue

- For VDSL IOP issue, please contact with support@draytek.com for different VDSL firmware.

Notes

Modifications

- None