

## Release Note for Vigor2850 Series

**Firmware Version: 3.6.8.5**

**Release Date: August 5, 2016**

**Applied Models:**

**Vigor2850/Vigor2850n/Vigor2850Vn/ Vigor2850i**

---

Vigor2850 series is a **VDSL2** router with **multi-subnet** for secure and efficient workgroup management. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

- File and Modem Code

(1) VDSL Firmware Version: 1414c3

(2) ADSL for Annex A Model,

- "v2850\_a\_3685" is used for modem code 211801(Standard).
- "v2850\_a2\_3685" is used for modem code 2121501.
- "v2850\_a3\_3685" is used for modem code 2211201.
- "v2850\_a4\_3685" is used for modem code 232201 (recommended for UK-SEG only)
- "v2850\_a5\_3685" is used for modem code 243601.
- "v2850\_a6\_3685" is used for modem code 243701.
- "v2850\_a7\_3685" is used for modem code 2431301.
- "v2850\_a8\_3685" is used for modem code 244001.
- "v2850\_a9\_3685" is used for modem code 2471201.

(3) ADSL for Annex B Model,

- "v2850\_b\_3685" is used for modem code 2111112. (Standard)
- "v2850\_b1\_3685" is used for modem code 2111302 (recommended for Czech only)
- "v2850\_b2\_3685" is used for modem code 2121302.(recommended for Slovakia only)
- "v2850\_b4\_3685" is used for modem code 214702.
- "v2850\_b5\_3685" is used for modem code 2111312.
- "v2850\_b6\_3685" is used for modem code 215202.
- "v2850\_b7\_3685" is used for modem code 246302.

## New Features

- Support TLS V1.2.

## Improvement

- Improved: Support parameters (HTTP/HTTPS trigger) for TR-069.
- Improved: Improvement for web portal.
- Improved: Add protection mechanism to filter TCP/IP SYN+FIN packet to fix TCP weakness.
- Corrected: Fixed the reboot error for SSL Test.
- Corrected: Fixed the reboot error for wrong SIP message.
- Corrected: Wrong Wi-Fi country code issue.

## Known Issue

- For VDSL IOP issue, please contact with [support@draytek.com](mailto:support@draytek.com) for different VDSL firmware.

## Notes

- None