NO: AP1101-2 V.1

Release Note for Vigor2862B Series

| Firmware Version: | 3.8.8.2 |
|-------------------|--------------------------|
| Release Type: | Critical |
| Applied Models: | Vigor2862B / Vigor2862Bn |

Vigor2862B/Bn is a VDSL2 router with multi-subnet for secure and efficient workgroup management. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. In which, Vigor2862B series can support VDSL2 Bonding. By connected to a pair of bonded VDSL line, it can get a doubled transmission rate, or get the same rate but over a longer distance. Besides, Vigor2862Bn has built-in Wireless LAN for wireless connection.

This is a critical update - You should upgrade such Vigor router immediately with firmware containing these improvements.

New Features

None.

Improvement

• This firmware includes improvements to harden the web interface against attacks. We have become aware of specific attacks against router, including DrayTek models where hackers have altered specific settings relating to your DNS servers and DHCP settings. You should urgently check those settings on your router. If they appear to have been tampered with, correct them and change your admin password and for any other config anomalies. Restore a config backup if you have one (from prior to the attack). We continue to investigate this issue but the first priority was to issue updated firmware.

File and Modem Code

For DSL models, there will be two folders: Bonding_VT1. The files in Bonding_VT1 named folder include different modem codes. If you're using a VDSL line, Bonding_VT1 named firmware may bring out better performance. Available modem codes for Annex A/Annex B are displayed as follows:

For Annex A Model,

- ➤ "Vigor2862_3.8.8.2_Bonding_en.7z" is used for modem code 776d07_772801 & 774307_771801
- "Vigor2862_3.8.8.2_Bonding_VT1_en.7z" is used for modem code 779517_773F01 & 776d07_772801

For Annex B Model,

- "Vigor2862_3.8.8.2_Bonding_en.7z" is used for modem code 773306_771502 & 773307_771C02
- "Vigor2862_3.8.8.2_Bonding_VT1_en.7z" is used for modem code 773306_771502 & 773307_771C02

Known Issue

• None.

RD NO: 107_05_18