Release Note for Vigor2925 Series

Firmware Version: 3.7.4 Release Date:March 13, 2014 Applied Models:

Vigor2925, Vigor2925n, Vigor2925n-plus, Vigor2925Vn-plus

Vigor2925 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- Add URL link for dashboard panel.
- Add station list and traffic graph for APM.
- Support VoIP function.
- Support CVM (Central VPN Management) function.
- Support dual 3G/LTE function.
- Support two USB modem status.
- Support IPv6 for SSH.
- Support AP load balance.
- Support AP Maintenance.
- Support Rogue AP detection.

Improvement

- Improved: Increase port redirection and open port rule number settings.
- Improved: Enhance WCF function.
- Improved: Add LAN access control.
- Improved: Add TR-069 port in management setting.
- Improved: Increase routed subnet IP pool count from 10 to 32.
- Improved: Modify the web page of Load-Balance/Route Policy by adding the Wizard mode and the Advance mode. In which, the wizard mode allows to configure frequently used settings of route policy via three setting pages. The detailed setting page of Advanced mode is modified by adding some notes.
- Improved: Support longer name for VPN host/server.
- Improved: Wireless wizard modifications.

- Improved: DHCP lease time for subnet.
- Improved: Able to block LINE app for PC and mobile phone.
- Improved: Support a note for Remote Dial-in User authenticating with LDAP server.
- Corrected: Force MPPE encryption for PPTP didn't work with MS-CHAP v2 authentication.
- Corrected: Fixed memory leak in the SSH.
- Corrected: Fixed the problem that WCF caused router reboot.
- Corrected: Online status information error.
- Corrected: Correct iPhone wireless connection dropped issue.
- Corrected: No reboot after finishing firmware upgrade.
- Corrected: SSL user can't join user group.
- Corrected: Web portal setup disappeared when the profile disabled.
- Corrected: Telnet command "sys tr get Int." caused router reboot.
- Corrected: Policy route issue.
- Corrected: L2TP mode could not display WAN IP.
- Corrected: Some WUI minor issues.

Known Issue

• The WAN port can not work well with Alcatel I-040G device. The quick solution is to add another switch between Vigor2925 and Alcatel I-040G.

Notes

Modifications

None