

Release Note for Vigor300B

Firmware Version: 1.0.8.2
Release Date: June 23, 2014
Applied Models: Vigor300B

Vigor300B, a firewall broadband router with multi-WAN interface, can connect to xDSL/cable/VDSL2/Ethernet FTTx. The multi-WAN and LAN switch facilitate unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe. The state-of-art routing feature, and multi-WAN provide integrated benefits for professional users and small offices.

New Features

- None.

Improvement

- Improved: Web Portal stability.
- Improved: Remove management port setting which may occupy port redirection.
- Improved: Add telnet timeout if not login in 60 seconds.
- Improved: Upgrade OpenSSL to 0.9.8za for some security issues.
- Fixed: CPU usage is too high when data flow monitor is enabled.
- Fixed: NAT Loopback to LAN More Subnet doesn't work.
- Fixed: Reboot with Customized Configurations bug.
- Fixed: When firewall default policy (block) is used, HTTP is still available for access.
- Fixed: Web portal still supports URL redirect when login mode is disabled.
- Fixed: WAN Priority Bits didn't work.
- Fixed: An error occurred in time object.
- Fixed: WCF (Web Content Filter) cannot be enabled when myVigor Portal changes Service Name from Commtouch to Cyren.
- Fixed: DDNS failover 3G WAN didn't work.
- Fixed: Daylight Saving didn't work for UTC+1(Ljubljana).

Known Issue

- None

Notes

Modifications

- None