

Release Note for Vigor300B

Firmware Version:	1.5.1.4
Release Type:	Normal
Applied Models:	Vigor300B

New Features

- None.

Improvement

- Improved: Improve Web GUI Security.
- Improved: Disable TR069 from WAN by default.
- Improved: Improve the OpenSSL security (CVE-2022-0778).
- Improved: Set the OpenVPN encryption version to TLS 1.2 by default.
- Corrected: An issue of Let's Encrypt certificate renew failure if enabling Access Control.
- Corrected: An issue of IKEv2 EAP VPN(H2L) failure if cut wrongly the subject alternative name of the local certification.

Known Issue

- The new firmware version 1.5.1.4 removes the support of the character "%" as the admin password to enhance the WebGUI security. If the character "%" is used as the admin password, please change the password before upgrading to the new firmware version. If the character "%" is used as the admin password and you've upgraded to the new firmware version without changing the password, please use the following CLI commands via Telnet/SSH to change the admin password.
-enable
-configure system
-admin_passwd