

Release Note for Vigor3900 Series

Firmware Version:	1.5.1.1
Release Type:	Critical
Applied Models:	Vigor3900

Due to the firmware size limitation, for devices using firmware version 1.0.5 or earlier, it is suggested to upgrade to firmware version 1.0.7.1 first before upgrading to version 1.0.8.x and later.

This is a critical update - You should upgrade such Vigor router immediately with firmware containing these improvements.

New Features

- None.

Improvement

Others

- Improved: Improved WebGUI security.
- Improved: Disable the local/remote port forwarding via SSH.
- Improved: Special character (e.g., `) is not allowed to use for User Profile.
- Corrected: An issue of unable to access WUI due to some reasons.
- Corrected: An issue of getting NTP time after the system reboot.
- Corrected: An issue that some outgoing TCP Packets were not NATed.
- Corrected: An issue that IP Bind Mac table could not be sorted alphabetically, correctly.
- Corrected: An issue of taking long time to display the main page after login.
- Corrected: An issue of failing to apply for Let's Encrypt certificate when Web Allow was disabled.

VPN

- Corrected: An issue that VPN Remote Dial-In User failed to resolve DNS over VPN when the local DNS server is used.
- Corrected: An issue of displaying IPsec Xauth's username in VPN connection management.
- Corrected: An issue of firewall rules not working for OpenVPN connections.
- Corrected: An issue of IPsec VPN connection stability.
- Corrected: An issue of saving IPsec Aggressive VPN PSK setting when the peer ID was empty.
- Corrected: An issue of creating Dial-In IKEV2 multiSA VPN connection when the server was behind NAT.

- Corrected: An issue of disconnecting VPN for L2TP over IPsec via the WebUI.
- Corrected: An issue that IPsec LAN to LAN VPN stopped passing traffics (a system reboot required).

Known Issue

- None.