

Release Note for Vigor3912 Series

Firmware Version:	4.4.3.6
Release Type:	Critical – Upgrade immediately to address urgent security issues or major system risks
Applied Models:	Vigor3912, Vigor3912S

New Features

- None.

Improvement

- Improved: Improve the Web GUI Security.
- Improved: Improve the stability of ACS firmware upgrade.
- Corrected: An issue where NAT loopback/openport did not work for IP Alias WAN and TCP.
- Corrected: An issue where the "Failover to" option in Policy Route disappeared when the rule was enabled.
- Corrected: An issue while viewing the dashboard, the router was busy due to a high number of BFP entries.
- Corrected: An issue where the Linux IP used a random MAC address that might cause trouble in Bind IP to MAC.
- Corrected: A certification generation issue where the local certificate list was suddenly empty, and generating new certificates did not work.

Known Issue

- None.