

# Release Note for VigorIPPBX 2820 Series

**Firmware Version: 3.5.0.1**

**Built Date: June 11, 2009**

**Applied Models: VigorIPPBX™ 2820**

---

**Notice:** Please upload system prompt (by default, it has stored in device). Access into Prompt Maintenance of web interface and upload *v2820pbx\_sysprompt.ivr*. Wait until IPPBX is ready.

- File and Modem Code

(1)For Annex A Model,

- "v2820pbx\_a\_350.\*" is used as standard.
- "v2820pbx\_a1\_350.\*" is used for modem code 211011.
- "v2820pbx\_a2\_350.\*" is used for modem code 2121501.
- "v2820pbx\_a3\_350.\*" is used for modem code 2211201.
- "v2820pbx\_a4\_350.\*" is used for modem code 232201 (Recommended for UK\_SEG).

(2)For Annex B Model,

- "v2820pbx\_b\_350.\*" is used as standard.
- "v2820pbx\_b1\_350.\*" is used for modem code 2111302.
- "v2820pbx\_b2\_350.\*" is used for modem code 2121302.
- "v2820pbx\_b4\_350.\*" is used for modem code 214702.
- "v2820pbx\_b5\_350.\*" is used for modem code 2111312.
- "v2820pbx\_b6\_350.\*" is used for modem code 215202.

## New Features

- None

## Improvement

- Fix the reboot issue when working with Netherlands PSTN gateway
- Improve call hold and call transfer function more robust.

## Known Issue

- Some SIP client can't hear a beep sound before a user speaks his voicemail message.

However, the user can leave a message still.

- For DTMF relay, user must use outband mode (RFC-2833) in IP phone, FXS and ISDN phone.
- This version does not support call routing and call park.
- VoIP T.38 fax relay function is not supported.
- The router is not stable when a user uses Foxy.
- A problem of Iptel 8# needs to be solved.
- NMAP scan problem needs to be solved.

## Notes

### *Modifications*

- None