

Release Note for VigorIPPBX 2820 Series

Firmware Version: 3.5.1

Built Date: July 23, 2009

Applied Models: VigorIPPBX™ 2820

- File and Modem Code

(1)For Annex A Model,

- "v2820pbx_a_351.*" is used as standard.
- "v2820pbx_a1_351.*" is used for modem code 211011.
- "v2820pbx_a2_351.*" is used for modem code 2121501.
- "v2820pbx_a3_351.*" is used for modem code 2211201.
- "v2820pbx_a4_351.*" is used for modem code 232201 (Recommended for UK_SEG).

(2)For Annex B Model,

- "v2820pbx_b_351.*" is used as standard.
- "v2820pbx_b1_351.*" is used for modem code 2111302.
- "v2820pbx_b2_351.*" is used for modem code 2121302.
- "v2820pbx_b4_351.*" is used for modem code 214702.
- "v2820pbx_b5_351.*" is used for modem code 2111312.
- "v2820pbx_b6_351.*" is used for modem code 215202.

New Features

- Support Wireless LAN

Improvement

- Fixed: problem occurred in RTP port map for iptel.org.
- Fixed: problem occurred in RTP port map for Netherlands PSTN gateway.
- Corrected: Router will reboot when calls an extension through auto attendant prompt and the extension is set for voicemail with “no answer”.
 - * Extension number “1002” is set for voicemail on “no answer”.
 - * In auto attendant, key “0” is set for calling the extension “1002”.
 - * When calling PBX SIP line, it plays auto attendant prompt.

Known Issue

- Some SIP client can't hear a beep sound before a user speaks his voicemail message. However, the user can leave a message still.
- For DTMF relay, user must use outband mode (RFC-2833) in IP phone, FXS and ISDN phone.
- This version does not support call routing and call park.
- VoIP T.38 fax relay function is not supported.
- The router is not stable when a user uses Foxy.
- NMAP scan problem needs to be solved.

Notes

Modifications

- None