Release Note for Vigor2915 Series

Firmware Version:	4.4.6.2
Release Type:	Critical – Upgrade immediately to address urgent security issues or major system risks
Applied Models:	Vigor2915, Vigor2915ac

Vigor2915 series is a dual band router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

New Features

- None.

Improvement

- Improved: Improve the WiFi Driver Security (CVE-2025 20710, CVE-2025-20715, CVE-2025-20716, CVE-2025-20718, CVE-2025-20719, CVE-2025-20720, CVE-2025 20724, CVE-2025-20733, CVE-2025-20734, CVE-2025-20736, CVE-2025-207337, CVE-2025 20738, and CVE-2025 20739).
- Improved: Add new TR-069 parameters for LTE SIM 1/2 priority by CLI.
- Improved: Add options to customize RSRP & RSRQ signal quality values, and display these values on the router login summary.
- Corrected: An issue with the failure to sync the DrayDDNS daily.
- Corrected: An issue with the device losing connection with VigorACS.
- Corrected: An issue with failure to configure TR-069 parameters by CLI.
- Corrected: An issue with stopping to send periodic inform to VigorACS server.
- Corrected: An issue with the failure to reboot the router from the VigorACS server.
- Corrected: An issue with the failure to use AES256 and set the Proposal to DH Group with a value higher than 14.
- Corrected: An issue with the failure to enable the "Ping Gateway IP" option for PPPoE under WAN>>Internet Access.
- Corrected: An issue with the failure to create DHCP option 15 under LAN>>General Setup, DHCP Server Customized Status.

Known Issue

- None.