Release Note for VigorAP 800

Firmware Version: 1.1.4
Release Date: March 10, 2014
Applied Models: VigorAP 800

"With this high cost-efficiency VigorAP 800, computers and wireless devices which are compatible with 802.11n can connect to the existing Ethernet network via this VigorAP800. 300Mbps wireless transmission rates is ideal for bandwidth-heavy tasks. Easy install procedures allow any computer users to setup a network environment in very short time - within minutes, even inexperienced users."

New Features

- None.

Improvement

- Improved: Remove unnecessary DHCP entry in DHCP table.
- Fixed: Failed to upgrade firmware by VigorACS V1.1.4_RC2.
- Fixed: Fix the problem of AirPrint.
- Fixed: When the wireless connection is up/down by schedule, users can't authenticate via RADIUS anymore.

Related Information

- Get the document, please visit
  http://www.draytek.com/user/PdInfoDetail.php?Id=122

- Get the new firmware, please visit
  http://www.draytek.com/user/SupportDownloads.php

- Get the customer service support, please visit
  http://www.draytek.com/user/ContactHeadquarters.php

- Get the regulatory compliance information
  http://www.draytek.com/user/AboutRegulatory.php

- Get information for global partners
  http://www.draytek.com/user/Globalpartners.php

Known Issue

- None

Notes

Modifications

- None