Release Note for VigorAccess DSL module

Firmware Version: 2.10.2.20.M
Built Date: July 2, 2009
Applied Models:
VigorAccess A24M, VigorAccess A24S
VigorAccess IVD Slave

New Features

- None

Improvement

- Change DSP code from E67.4.78 to E67.4.128 on AnnexA to solve port lockup.
- Change DSP code from E67.1.87 to E67.1.128 on AnnexM to solve port lockup.
- Change DSP code from E74.1.22 to E74.1.44 on AnnexB to solve port lockup.
- Fixed: IOP problem in some web browsers.
- Fixed: Crash and reboot problem of 2.10.2.20.A on TTML.
- IGMP leave message was sent out on each IGMP group respectively. Now, only the last IGMP leave message will be sent out on each IGMP group.
- Fix the GAG errors for factory default settings while rebooting the device.
- Change FAN detection to avoid system hang.

Known Issue

- Remove firmware upgrade web page temporarily. We found some IOP problem with some web browser. It will cause system crash. We will fix it in next version.

Notes

- None.