Release Note for VigorPro 5300 Series

Firmware Version: 3.3.6.1
Built Date: November 05, 2012
Applied Models: VigorPro 5300

New Features

- None.

Improvement

- Corrected: The firewall rule doesn't work when the filter action is set with "Pass If No Further Match".
- Corrected: License can't be activated well due to a proxy installed between the router and the server.
- Corrected: User management can not be displayed on login web page normally in Safari browser.
- Fixed: The Web Content Filter's cache maintenance would cause router reboot.
- Fixed: The telnet command (*csm wcf server)* would cause the router reboot.
- Improved: Reduce the opportunity of Anti-Spam happened query server timeout.
- Improved: When the cache for Web Content Filter is changed into None, the cache will clean all the data in it.
- Improved: The web authentication for user management allows you to choose HTTPS or HTTP (configured in **User management>>General Setup**).

Known Issue

- None

Notes

- None