Release Note for Wireless APP (Android)

Firmware Version:	1.2.0
Release Type:	Normal - Upgrade recommended when convenient
Applied Models:	See below

DrayTek Wireless APP is an ideal mobile application for on-premises VigorAP configuration and monitoring. It allows you to easily configure and manage the Mesh Wireless network with the following key benefits:

- Intuitively and easily set up a Vigor Mesh group from scratch
- Scan and sync configurations automatically to newly added VigorAPs
- Basic configuration for WiFi name / password, channel, admin password, TR-069 and etc
- Monitor the Mesh node (APs) for WiFi signal strength and topology
- Monitor WiFi clients with device names, signal strength, real-time data rates and etc

New Features

- Support the following functions for Group AP on the Device page.
    - Delete/Clear All nodes.
    - Discover/List/Add nodes.
    - Display unauthorized/online/offline status for AP.
    - Enable/disable the Root AP on the Dashboard page.
    - Allow to set authentication username/password for nodes.
    The new function is available for the following AP model:
      VigorAP 903 (with firmware 1.4.7 and above)
      VigorAP 802 (with firmware 1.4.8 and above)
      VigorAP 912C (with firmware 1.4.8 and above)
      VigorAP 960C (with firmware 1.4.6 and above)
      VigorAP 1060C (with firmware 1.4.7 and above)
      VigorAP 1000 (with firmware 1.4.5 and above)
      VigorAP 918 (with firmware 1.4.5 and above)
      VigorAP 920 (with firmware 1.4.5 and above)

Improvement

- None.

Known Issue

- None.

Applied Models

- VigorAP 802 (with firmware 1.4.0 and above)
- VigorAP 903 (with firmware 1.4.0 and above)
- VigorAP 912C (with firmware 1.4.0 and above)
- VigorAP 918R (with firmware 1.4.0 and above)
- VigorAP 920R (with firmware 1.4.0 and above)
- VigorAP 960C (with firmware 1.4.0 and above)
- VigorAP 1000C (with firmware 1.4.0 and above)
- VigorAP 1060C (with firmware 1.4.0 and above)
- Vigor2765 Series (with firmware 4.3.1 and above)
- Vigor2862ac/Vac/Lac Series (with firmware 3.9.5 and above)
- Vigor2865 Series (with firmware 4.2.2 and above)
- Vigor2926ac/Vac/Lac Series (with firmware 3.9.5 and above)
- Vigor2927 Series (with firmware 4.2.4 and above)