Release Note for Vigor120 Series

Firmware Version:	3.7.2
Release Type:	Normal
Applied Models:	Vigor120(V2)

New Features

- None.

Improvement

- This firmware includes improvements to harden the web interface against attacks. We have become aware of specific attacks against router, including DrayTek, models where hackers have altered specific settings relating to your DNS servers and DHCP settings. You should urgently check those settings on your router. If they appear to have been tampered with, correct them and change your admin password and check for any other config anomalies. Restore a config backup if you have one (from prior to the attack). We continue to investigate this issue but the first priority was to issue updated firmware.

Known Issue

- None.

File and Modem Code

(1)For Annex A Model,
- "v12x_a_v372" is used for modem code 321311. (Standard)
- "v12x_a1_v372" is used for modem code 310801.
- "v12x_a2_v372" is used for modem code 310811.
- "v12x_a3_v372" is used for modem code 3211201
- "v12x_a4_v372" is used for modem code 332201(recommended for U.K.).
- "v12x_a5_v372" is used for modem code 343601.
- "v12x_a6_v372" is used for modem code 343701 (recommended for Italy).
- "v12x_a7_v372" is used for modem code 3431301.
- "v12x_a8_v372" is used for modem code 344001.
- "v12x_a9_v372" is used for modem code 344101.

> ➢ "v12x_a10_v372" is used for modem code 3471101.

(2)For Annex B Model,

> ➢ "v12x_b_v372" is used for modem code 311112. (Standard)
> ➢ "v12x_b1_v372" is used for modem code 3101212.
> ➢ "v12x_b2_v372" is used for modem code 3101332.
> ➢ "v12x_b3_v372" is used for modem code 311102.
> ➢ "v12x_b4_v372" is used for modem code 346302.

RD NO: 107_05_25