Release Note for Vigor120 Series

Firmware Version: 3.2.2.1
Built Date: June 18, 2009
Applied Models:
Vigor120

- File and Modem Code
  (1)For Annex A Model,
    - "v120_a_v322" is used for modem code 321311. (Standard)
    - "v120_a1_v322" is used for modem code 310801.
    - "v120_a2_v322" is used for modem code 310811.
    - "v120_a3_v322" is used for modem code 3211201
    - "v120_a4_v322" is used for modem code 332201.
    - "v120_a5_v322" is used for modem code 343601.
    - "v120_a6_v322" is used for modem code 343701.

New Features

- Support a new telnet command – `adsl showbins`.

Improvement

- Cancel the limitation on the same subnet for WAN IP/Gatway IP of WUI.
- Corrected: WAN IP Alias cannot be cleared.
- Corrected: Fixed IP address cannot be saved.
- Corrected: Typing error for PPPoE user name (bandwithbar.co.za) for South Africa ISP.

Known Issue

- None

Notes

Modifications

- None