Release Note for Vigor120 Series

Firmware Version: 3.7.1.2
Release Date: August 20, 2013
Applied Models:
Vigor130

- File and Modem Code
  (1)For Annex A Model,
    - VDSL 548006 & ADSL 544401 (Standard)
    - VDSL 547916 & ADSL 544411 will be used for Modem 1.
    - VDSL 550e06 & ADSL 551001 will be used for Modem 2.
    - VDSL 551506 & ADSL 551501 will be used for Modem 3.
  (2)For Annex B Model,
    - VDSL 548006 & ADSL 544512 (Standard)
    - VDSL 542016 & ADSL 535112 will be used for Modem 1.
    - VDSL 533d06 & ADSL 535902 will be used for Modem 2.
    - VDSL 548006 & ADSL 544512 will be used for Modem 3.

New Features

- None

Improvement

- Improved: Quick start wizard supports VLAN tag configuration.
- Corrected: VLAN tag settings cannot be saved if DSL mode is "Auto".
- Corrected: IPv6RD does not work when IPv4 connection is configured with PPPoE.
- Corrected: The router system would crash after configuring DHCPv6 settings.
- Corrected: Mail Alter function cannot be enabled.
- Corrected: The function of SNMP works slowly and often timeout.
- Corrected: Wrong screen display on Online Status for PPPoE connection.

Known Issue

- None

Notes

Modifications

- None