Release Note for Vigor2700 Series

Firmware Version: 2.8.2.1
Date: October 08, 2008
Applied Models:
Vigor2700Ge, Vigor2700e

- File and Modem Code
  (1)For Annex A Model,
    - "v2k7ge_a_2821.xxx " is used for modem code 121201. (Standard)
    - "v2k7ge_a1_2821.xxx " is used for modem code 113111.
    - "v2k7ge_a2_2821.xxx " is used for modem code 131701. (Recommended for UK-SEG)
    - "v2k7ge_a3_2821.xxx " is used for modem code 1401201. (Recommended for USA or for G..lite environment)
    - "v2k7ge_a4_2821.xxx " is used for modem code 1411301.

  (2)For Annex B Model,
    - "v2k7ge_b_2821.xxx" is used for modem code 131812. (Standard)
    - "v2k7ge_b1_2821.xxx" is used for modem code 113112.
    - "v2k7ge_b2_2821.xxx" is used for modem code 1211202.
    - "v2k7ge_b3_2821.xxx" is used for modem code 1311302. (Recommended for Germany)
    - "v2k7ge_b4_2821.xxx" is used for modem code 1401302.
    - "v2k7ge_b5_2821.xxx" is used for modem code 1411402.
    - "v2k7ge_b6_2821.xxx" is used for modem code 142112. (support T1.413 Annex B, Recommended for Spain)
    - "v2k7ge_b7_2821.xxx" is used for modem code 142402.

New Features

- None

Improvement

- Corrected: WLAN client can't get IP address from DHCP server no matter any Security Mode (e.g., WEP, WPA...) is selected.
- Corrected: Factory default will be failed on Vigor2700Ge when the wireless card exists.

Known Issue

- None

Notes

Modifications

- None