Release Note for Vigor2710 Series

Firmware Version:	3.7.0
Release Type:	Normal
Applied Models:	Vigor2710, Vigor2710n, Vigor2710Vn, Vigor2710VDn

New Features

- Add an option to disable / enable "EAPOL Key Retries" (Wireless LAN(2.4GHz) >> Security Settings), so system administrator can configure EAPOL retries.

Improvement

- None.

Known Issue

- None

File and Modem Code

(1) For Annex A Model,
- "v2710_a_370" is used for modem code 211011. (Standard)
- "v2710_a1_370" is used for modem code 211801.
- "v2710_a2_370" is used for modem code 2121501.
- "v2710_a3_370" is used for modem code 2211201.
- "v2710_a4_370" is used for modem code 232201. (Recommended for UK – SEG)
- "v2710_a5_370" is used for modem code 243601.
- "v2710_a6_370" is used for modem code 243701.
- "v2710_a8_370" is used for modem code 244001.
- "v2710_a7_370" is used for modem code 2431301.
- "v2710_a9_370" is used for modem code 2471201.
- "v2710_a10_370" is used for modem code 252901.

(2) For Annex B Model,
- "v2710_b_370" is used for modem code 2111112. (Standard)
- "v2710_b1_370" is used for modem code 2111302. (Recommended for Attel Czech only)
- "v2710_b2_370" is used for modem code 2121302 (recommended for Slovskia

only).

- ➤ "v2710_b4_370" is used for modem code 214702.
- ➤ "v2710_b5_370" is used for modem code 2111312.
- ➤ "v2710_b6_370" is used for modem code 215202.
- ➤ "v2710_b7_370" is used for modem code 246302.

RD NO: 106_12_01