Release Note for Vigor2763 Series

Firmware Version:	4.5.1
Release Type:	Critical – Upgrade immediately to address urgent security issues or major system risks
Applied Models:	Vigor2763, Vigor2763ac, Vigor2763Vac

New Features

- None.

Improvement

- Improved: Improve the Web GUI Security.
- Improved: Add SNMP OID for WAN uptime.
- Improved: Comply with EN 18031 cybersecurity requirements.
- Improved: Improve the WiFi Driver Security (CVE-2025-20681~20684, CVE-2025-20688~20692).
- Improved: Add an option to enable/disable the force password change when using the ".def" file.
- Corrected: An issue that the router rebooted when it was provisioned by ACS with an XML file that included specific VPN settings.
- Corrected: An issue that an unnecessary object menu appeared in the Objects Setting.
- Corrected: Router reboot issues related to WCF, VoIP/KMC56 buffer leakage, TR-069, and long URL.

Known Issue

- None.

File and Modem Code

- "Vigor2763_v4.5.1_STD.zip" provides Annex A modem code 77B507_775401, 77B506_775401 and Annex B 779B07_774C12, 779906_774402
- " Vigor2763_v4.5.1_MDM1.zip " is used for modem code77C817_775A11 77C717_775A11 and Annex B 77C717_775A12, 779B07_774C12