Release Note for Vigor2765 Series

Firmware Version:	4.0.4
Release Type:	Normal
Applied Models:	Vigor2765, Vigor2765ac

Vigor2765 is a VDSL2 35b router which is suitable for speed-wanted customers. With high throughput performance and secured broadband connectivity provided by Vigor2765, you can simultaneously engage these bandwidth-intensive applications, such as high-definition multimedia content, online music, movie streaming and file sharing.

New Features

● None.

Improvement

● Improved: Make improvement for VPN performance.
● Improved: Remove System Maintenance >> Modem Code Upgrade page.
● Corrected: Unable to pop-up the message related to the link between 2.4G and 5G after changing the channel bandwidth on Wireless LAN >> Advanced Setting.
● Corrected: Router rebooted constantly after restoring a specific configuration file.
● Corrected: Router rebooted as soon as the SSH session from a LAN PC times out.
● Corrected: Unable to display correct image on Dashboard.
● Corrected: MPoA WAN setting was missing in Quick Start Wizard.
● Corrected: Unable to display correct channel list for WLAN 5G after changing the country code.

Known Issue

● None.

Notes

● Vigor2765ac does not support WDS for wireless 2.4GHz.