Release Note for Vigor2765 Series

Firmware Version:	4.3.1
Release Type:	Normal
Applied Models:	Vigor2765, Vigor2765ac, Vigor2765Vac (for tender case)

Vigor2765 is a VDSL2 35b router which is suitable for speed-wanted customers. With high throughput performance and secured broadband connectivity provided by Vigor2765, you can simultaneously engage these bandwidth-intensive applications, such as high-definition multimedia content, online music, movie streaming and file sharing.

New Features

- Support Mesh network.
- Support multi-language of WUI.
- Support VPN Graph (on Diagnostics).
- Support Hardware acceleration with QoS.
- Support WPA3/OWE for wireless LAN 2.4G/5G.
- Support TOTP(2FA) authentication mechanism for administrator password setup.

Improvement

- Improved: Support full wildcard for use by DNS Forwarding setting.
- Improved: Optimize the web pages of LAN DNS and DNS Forwarding.
- Improved: Add color labels to express the different port speeds on the dashboard.
- Improved: Change the API String of "VibeActiveMedia.com" on SMS profile list.
- Improved: Support two ISP accounts (PPPoE/PPPoA) with the same WAN interface.
- Improved: Add a pop-up window for displaying an IP object or IP group profile is in use.
- Improved: Support hostname setting used on Access List from the Internet (System Maintenance>>Management).
- Corrected: An issue of LAN DNS operation.
- Corrected: An issue of restoring VPN backup file to Vigor router.
- Corrected: An issue of setting keyword group by telnet command.
- Corrected: An issue of DHCP IP pool count error if using "/29" IP Routed Subnet.
- Corrected: An issue that interfaces chosen for Filter Rule Direction (Advanced) would be unselected.
- Corrected: An issue of time zone displayed on Mail Alert and Notification Mail when Daylight Saving was enabled.

- Corrected: An issue of schedule profile selection arrangement on VPN and Remote Access>>Remote Dial-in User.

Known Issue

- None.

Notes

- Vigor2765ac only supports WDS in wireless 5G.
- This version allows up to 4 LAN subnets to be configured. To avoid continuous system reboot, only the RST file can be used for firmware downgrading.

File and Modem Code

- "Vigor2765_v4.3.1_STD.zip" provides Annex A modem code 8B0F07_8B0701, 8B2607_8B0B01 and Annex B 8B2607_8B0B02, 8B2817_8B0812.
- "Vigor2765_v4.3.1_MDM1.zip" provides Annex A modem code 8B1117_8B0701, 8B0F07_8B0701 and Annex B 8B2817_8B0812, 8B2607_8B0B02.
- "Vigor2765_v4.3.1_MDM2.zip" provides Annex A modem code 8D1917_8D0C11, 8D1507_8D0901 and Annex B 8D1917_8D0C12, 8B2817_8B0812.
- "Vigor2765_v4.3.1_MDM3.zip" provides Annex A modem code 77C717_8D0C11, 8D1507_8D0901 and Annex B 77C717_8D0C12, 8B2607_8B0B02.