Release Note for Vigor2830n V2

Firmware Version:	3.8.5
Release Type:	Normal
Applied Models:	Vigor2830n V2

Vigor2830n V2 is an ADSL2+ router. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The gigabit WAN2 and 4-port gigabit LAN switch facilitates unified communication applications in business CO/remote site to handle large data from subscribed fatter pipe.

New Features

- None.

Improvement

- Corrected: WPA2 KRACK vulnerability issue which affected Wireless WAN mode only. This issue affects all wireless clients so you should check your laptops, phones and all other wireless clients to see if they need updated software/firmware. Search for "WPA2 KRACK" with your vendor. See *https://www.draytek.com/en/news/news/2017/how-are-draytek-wireless-products-affected-by-the-wpa2-krack-vulnerability/*

File and Modem Code

Available modem codes for Annex A/Annex B are displayed as follows:

For Annex A Model,
- "Vigor2830n-v2_v3.8.5-00_en.zip" is used for modem code 548006_544401 & 560816_552011
- "Vigor2830n-v2_v3.8.5-01_en.zip" is used for modem code 567517_562301 & 566f07_562701
- "Vigor2830n-v2_v3.8.5-02_en.zip" is used for modem code 574307_571801 & 573807_571701

For Annex B Model,
- "Vigor2830n-v2_v3.8.5-00_en.zip" is used for modem code 548006_544512 & 551716_553312

➢ "Vigor2830n-v2_v3.8.5-01_en.zip" is used for modem code 565607_567002 & 565606_567002

➢ "Vigor2830n-v2_v3.8.5-02_en.zip" is used for modem code 573307_571c02 & 565607_567002

Known Issue

● None