Release Note for Vigor2832 Series

Firmware Version:	3.8.3.4
Release Type:	Normal
Release Date:	March 30, 2017
Applied Models:	Vigor2832, Vigor2832n

Vigor2832 series is an ADSL2/2+ router. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

File and Modem Code

Available modem codes for Annex A/Annex B are displayed as follows:

For Annex A Model,
➢ "Vigor2832_v3.8.3.4-00_en.zip" is used for modem code 06-06-01-07-00-01.

For Annex B Model,
➢ "Vigor2832_v3.8.3.4-00_en.zip" is used for modem code 06-06-00-02-01-02.

New Features

- Support the function of Hotspot Web Portal.
- Support new 2.4G wireless driver.
- Support Airtime Fairness.

Improvement

- Improved: Configure ALG related function via web user interface.
- Improved: Improve NAT and Routing performance.
- Improved: Central management for AP(s) via LAN-to-LAN VPN.
- Improved: Add an Alert message for WAN budget, if Hardware Acceleration is enabled.
- Improved: Add "MS-CHAPv2 Only" option for Dial-In PPP Authentication.
- Corrected: Unable to resolve the most DNS domain via VPN remote dial-in change default route, if DNS Security was enabled.
- Corrected: Unable to receive RIP packets from other routers if RIP function was enabled.
- Corrected: NAT Loopback occurred when LAN routing was running.
- Corrected: TCP port 8001 and 8043 responded on WAN.
- Corrected: VLAN did not work correctly under some specific environment.

Known Issue

- None