Release Note for Vigor2832 Series

Firmware Version:	3.8.9.1
Release Type:	Normal
Applied Models:	Vigor2832, Vigor2832n

Vigor2832 series is an ADSL2/2+ router. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

File and Modem Code

Available modem codes for Annex A/Annex B are displayed as follows:

For Annex A Model,

➢ "Vigor2832_v3.8.9.1-00_en.zip" is used for modem code 06-06-01-07-00-01.

For Annex B Model,

➢ "Vigor2832_v3.8.9.1-00_en.zip" is used for modem code 06-06-00-02-01-02.

New Features

● None.

Improvement

● Corrected: The settings in APP Enforcement Profiles were messed up, after upgrading the firmware to Version 3.8.9.
Suggestion: Choose one of the following methods to upgrade the router firmware.
- Upgrade the firmware from the old version to new version (V3.8.9.1) directly.
- Upgrade the firmware to V3.8.9 by using "x.all". Do not modify the APP profile configuration and then upgrade the firmware to 3.8.9.1.

● Corrected: Vigor router reboot randomly due to incompliant with TR-069 server.

Known Issue

- None