Release Note for Vigor2832 Series

Firmware Version:	3.9.6.1
Release Type:	Normal
Applied Models:	Vigor2832, Vigor2832n

Vigor2832 series is an ADSL2/2+ modem router with an alternative Gigabit Ethernet WAN port for load-balancing or failover. It has 4 Gigabit Ethernet LAN ports and 2 USB ports which can be used for 3G/4G WAN, temperature sensor, or NAS application. Models with built-in 802.11n Wi-Fi are available.

File and Modem Code

"Vigor2832_v3.9.6.1-00_en.zip" provides Annex A modem code 06-06-01-07-00-01, and Annex B modem code 06-06-00-02-01-02.

New Features

- None.

Improvement

- Improved: Improve Web GUI Security.
- Improved: Improve the OpenSSL security (CVE-2022-0778).
- Corrected: An issue of working with StarLink.
- Corrected: A display issue of IP log related to Let's Encrypt certificate.
- Corrected: An issue of NAT performance for tagging/untagging packets.
- Corrected: An issue of restoring config through HTTPS URL via VigorACS.
- Corrected: An issue of firmware damage due to firmware upgrade from 3.9.5 to 3.9.6.
- Corrected: A display issue of statistics for responding to "AP Discovery" on VigorACS.
- Corrected: An issue of port 443 opened even if the HTTPS server & SSL VPN service were disabled.

Known Issue

- None.