Release Note for Vigor2850 Series

Firmware Version: 3.6.0
Built Date: December, 12, 2011
Applied Models:
Vigor2850/Vigor2850n/Vigor2850Vn

Vigor2850 series is a **VDSL2** router with **multi-subnet** for secure and efficient workgroup management. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

- ● File and Modem Code
  (1)For Annex A Model,
  - ➢ "v2850_a_360" is used for modem code 211801(Standard).
  - ➢ "v2850_a2_360" is used for modem code 2121501.
  - ➢ "v2850_a3_360" is used for modem code 2211201.
  - ➢ "v2850_a4_360" is used for modem code 232201 (recommended for UK-SEG only)
  - ➢ "v2850_a5_360" is used for modem code 243601.
  - ➢ "v2850_a6_360" is used for modem code 243701.
  - ➢ "v2850_a7_360" is used for modem code 2431301.
  - ➢ "v2850_a8_360" is used for modem code 244001.
  - ➢ "v2850_a9_360" is used for modem code 2471201.

  (2)For Annex B Model,
  - ➢ "v2850_b_360" is used for modem code 2111112. (Standard)
  - ➢ "v2850_b1_360" is used for modem code 2111302 (recommended for Czech only)
  - ➢ "v2850_b2_360" is used for modem code 2121302.(recommended for Slovakia only)
  - ➢ "v2850_b4_360" is used for modem code 214702.
  - ➢ "v2850_b5_360" is used for modem code 2111312.
  - ➢ "v2850_b6_360" is used for modem code 215202.
  - ➢ "v2850_b7_360" is used for modem code 246302.

New Features

- ● Support IPv6.

Improvement

- None.

Known Issue

- None

Notes

Modifications

- None