Release Note for Vigor2850 Series

Firmware Version: 3.6.2
Built Date: May 14, 2012
Applied Models:
Vigor2850/Vigor2850n/Vigor2850Vn/ Vigor2850i

Vigor2850 series is a **VDSL2** router with **multi-subnet** for secure and efficient workgroup management. It integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

- File and Modem Code
  (1) VDSL Firmware Version: 1412f0
  (2) ADSL for Annex A Model,
    - "v2850_a_362" is used for modem code 211801(Standard).
    - "v2850_a2_362" is used for modem code 2121501.
    - "v2850_a3_362" is used for modem code 2211201.
    - "v2850_a4_362" is used for modem code 232201 (recommended for UK-SEG only)
    - "v2850_a5_362" is used for modem code 243601.
    - "v2850_a6_362" is used for modem code 243701.
    - "v2850_a7_362" is used for modem code 2431301.
    - "v2850_a8_362" is used for modem code 244001.
    - "v2850_a9_362" is used for modem code 2471201.
  (3) ADSL for Annex B Model,
    - "v2850_b_362" is used for modem code 2111112. (Standard)
    - "v2850_b1_362" is used for modem code 2111302 (recommended for Czech only)
    - "v2850_b2_362" is used for modem code 2121302.(recommended for Slovakia only)
    - "v2850_b4_362" is used for modem code 214702.
    - "v2850_b5_362" is used for modem code 2111312.
    - "v2850_b6_362" is used for modem code 215202.
    - "v2850_b7_362" is used for modem code 246302.

New Features

- Support ISDN backup.
- Support Smart Bandwidth Limit.
- Support Port Triggering.

- Support DSCP Re-tag according to QoS class.

Improvement

- Improved: Change VDSL firmware version to 1412f0.
- Improved: Show status on VPN profile.

Known Issue

- None

Notes

Modifications

- None