Release Note for Vigor2866ax Series

Firmware Version:	4.3.2.1
Release Type:	Normal
Applied Models:	Vigor2866ax / Vigor2866Vax / Vigor2866LVax

Vigor2866ax series features in G.fast, VDSL2 35b Super Vectoring, Gigabit throughput, App-Based QoS, VPN Client/Server, and WiFi 6.

New Features

- None.

Improvement

- Corrected: An issue of system stability and router reboot.
- Corrected: An issue of self-signed certificate regeneration automatically of Vigor router before expiration.
- Corrected: An issue of Hardware Acceleration failed to accelerate the WAN to LAN sessions in the routing mode.

File and Modem Code

- "Vigor2866ax_v4.3.2.1_STD.zip" provides Annex A modem code 123230_02 and 123210_30, and Annex B modem code 123230_022 and 123210_302.

Known Issue

- The wireless clients might encounter unexpected trouble (e.g., unable to use the printer on LAN) while accessing into Internet if the hardware acceleration is enabled.
  To skip hardware acceleration for certain devices, the following telnet command can be used:
  ```
  ppa -E -e 1
  ppa -E -a AA:BB:CC:XX:XX:XX nat|bridge|ipsec
  ```