Release Note for Vigor2915 Series

Firmware Version:	4.4.3.1
Release Type:	Normal - Upgrade recommended when convenient
Applied Models:	Vigor2915, Vigor2915ac

Vigor2915 series is a dual band router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth.

New Features

- Support new WCF suppliers.

Improvement

- Improved: Improve Web GUI Security (CVE-2024-23721).
- Improved: Support to show license log related to MyVigor on Web Syslog.
- Improved: Improve the TR-069 cookie for connecting VigorACS.
- Improved: Support the number of available countries up to 252.
- Improved: Support the alias-based and instance wildcards for TR069.
- Improved: Support IPv6 TCP DNS block used for CSM>>DNS Filter Profile.
- Improved: Support the admin password on the AP Management WLAN profile with more than 16 characters.
- Corrected: An issue with failure to upgrade the firmware via VigorACS.
- Corrected: An issue that local ping was forwarded to WAN by a route policy.
- Corrected: An issue with failure to restore the certificate issued by other CPE.
- Corrected: An issue with the TX/RX rate not displayed on the page Data Flow Monitor.
- Corrected: An issue that the route policy did not work if the WAN IP Alias was enabled.
- Corrected: An issue that Periodic Inform Settings defined on the System Maintenance >> TR-069 Setting not working after the router's system reboot.

Known Issue

- None.