Release Note for Vigor2925 Series

Firmware Version: 3.7.4.1
Release Date: May 09, 2014
Applied Models:
Vigor2925, Vigor2925n, Vigor2925n-plus, Vigor2925Vn-plus

Vigor2925 series is a broadband router which integrates IP layer QoS, NAT session/bandwidth management to help users control works well with large bandwidth. The state-of-art routing feature, VPN security, and Dual-WAN provide integrated benefits for professional users and small offices.

New Features

- None.

Improvement

- Corrected: Can not set USB WAN for SIP account via Telnet command.
- Corrected: Fixed that wireless LAN can't get correct subnet index from DHCP server.
- Corrected: FXS speaker gain display was incorrect in VoIP call status web page.
- Corrected: Call log information was not complete when the call was made by Digit Map.
- Corrected: WAN1 is up but Default Route disappears after WAN2 PPPoE is down.
- Corrected: Remove "Central AP Management >> Function Support List" for UK.
- Improved: Merge CVM schedule profiles (index number from 9 to 16).
- Improved: Add VLAN tag for WAN IPv6 packets if WAN VLAN tag is enabled.
- Improved: Modifications for Brazil Anatel (VoIP) conformance test.
- Improved: Send a DHCPv6 release message before DHCPv6 WAN sends any solicitation.
- Improved:Support a list to bypass NAT acceleration for specific port (service).

Known Issue

- The WAN port can not work well with Alcatel I-040G device. The quick solution is to add another switch between Vigor2925 and Alcatel I-040G.

Notes

Modifications

- None