

Release Note for Vigor2928 Series

Firmware Version:	5.4.4.3
Release Type:	Critical – Upgrade immediately to address urgent security issues or major system risks
Applied Models:	Vigor2928, Vigor2928be, Vigor2928be-4G, Vigor2928be-5G

Vigor2928 Series is a high-performance 10G Multi-WAN VPN router designed for next-generation business networking. Featuring up to 10Gbps Multi-WAN connectivity, advanced routing, intelligent traffic management, Wi-Fi 7 (IEEE 802.11be), and VigorShield cybersecurity services with enterprise-grade VPN, it provides a secure, high-performance, and future-ready networking platform for modern businesses.

New Features

- None.

Improvement

- Corrected: An issue where Teleworker VPN users assigned an IP address from a LAN subnet other than LAN1 did not receive the 2FA pop-up and were disconnected after the 2FA timeout.

Known Issue

- None.

Note

- Please ensure that you use the ".rst" firmware file when recovering the router. Note that uploading the ".rst" file will reset the router to factory default settings.
For certain models, a separate ".rst" (reset) firmware file may not be provided. If the ".rst" version is not available, please manually rename the file extension of the ".all" or ".sfw" firmware file to ".rst" to create an equivalent RST firmware file.
Example:
Rename Vigorxxxx_1.2.3.4.sfw → Vigorxxxx_1.2.3.4.rst
Please ensure you back up your configuration before applying a ".rst" firmware, as all settings will be erased during the process.